From: Sent: To: CC: Subject: Attachments:	Barbara Brown -MDE- [barbara.brown1@maryland.gov] 5/24/2019 2:56:49 PM Weissbart, Erich [Weissbart.Erich@epa.gov]; Pizarro, Luis [pizarro.luis@epa.gov]; Hennessy, Joel [Hennessy.Joel@epa.gov]; Prince, Ruth [Prince.Ruth@epa.gov]; Oduwole, Moshood [Oduwole.Moshood@epa.gov] Jennifer Sohns -MDE- [jennifer.sohns@maryland.gov] Fwd: Process Area Material Analysis Rpt_WO_19052018_Ver_1_001_Final - Processing Area.pdf; Copy of 19052018_EDD - Processing Area.xls
Forwarded message	
Barbara/Jennifer:	
Attached please find the analytical results from the samples that were taken from the process area on May 20, 2019. Samples C-1 and C-2 are from the excavation face; the excavation face is now covered and capped. The other samples are from the processed material piles.	
Please call if you have any questions or require additional information.	
Thanks.	
Pete	
Peter Haid	
Senior Direc	tor of Environmental
TRADEPOINT ATLANTIC	
1600 Sparro	ws Point Boulevard
Baltimore, Maryland 21219	

phaid@tradepointatlantic.com



Barbara Brown MDE-LRP-VCP Section Head direct 410 537 3212 general 410 537 3493

<u>Click here</u> to complete a three question customer experience survey.